



Tesla Motors TX, Inc.  
 6500 Cedar Springs Road  
 Dallas, TX, US 75235  
 Ph.: 1-214-736-0587

# Invoice

**SERVICE DEPARTMENT HOURS**  
 Mon-Fri 8:00 a.m. - 5:00 p.m  
 Sat-Sun Sat-Sun: Closed

Invoice date	Invoice number
24-Mar-2026	3000S0016314547
Service#	
SV02937DC9	
Due Date	PO Number
24-Mar-2026	
Date/Time Received	Date/Time Promised
23-Mar-2026 13:59:21	24-Mar-2026 18:00:44
Odometer In	Odometer Out
7984 Miles	7985 Miles
Ready Date	
24-Mar-2026 11:45:51	
Service Advisor	
Evan Opgenorth	

**Paid**

Bill To
[Redacted]

Mobile Phone	Additional Phone	Vehicle Identification Number	
[Redacted]		7G2CEHED6TA08	[Redacted]
Year	Model	License Plate Number	Colour
2026	CYBERTRUCK		

Job	Description Of Work	Amount (USD)
1	<p><b>Concern:</b> Check tire pressure and condition</p> <p><b>Repair Notes:</b> We performed a courtesy service on your vehicle, which included checking and adjusting tire pressure. Inspecting tire tread depth and topping off the windshield washer fluid.</p> <p>Tire replacement recommended            Replacement: No            Tire rotation recommended            Rotation: No</p> <p><b>Correction Automated Tire Pressure Check (Adjustment Needed)</b></p> <p><b>Correction Check Tire Tread Depth</b></p> <p><b>Correction Windshield Washer Fluid - Top Off</b></p> <p style="text-align: right;">Pay Type: Goodwill-Internal</p>	<b>0.00</b>
2	<p><b>Concern:</b> Cybertruck PCS2 Replacement</p> <p><b>Repair Notes:</b> Tech lifted up the Vehicle. Removed Trunk Bed and drain the Coolant system. Removed and replaced the Power Conversion System. Firmware updated, vacuumed &amp; refilled Coolant system and performed Coolant air purged. Tested charging system with Shop Mobile, Wall and Supercharger. Performed Thermal system test and post repair validation test drive. Verified Vehicle is operating as normal at this time.</p> <p><b>Correction Power Conversion System - Remove and Replace</b></p>	<b>0.00</b>

	<p><b>Parts Replaced or Added</b></p> <table> <thead> <tr> <th>Part</th> <th>Quantity</th> </tr> </thead> <tbody> <tr> <td>FERRITE ROUND CABLE FOR HARNESS(2134590-00-A)</td> <td>1.00</td> </tr> <tr> <td>POWER CONVERSION SYSTEM - 48AMP(1777777-T2-G)</td> <td>1.00</td> </tr> </tbody> </table> <p style="text-align: right;">Pay Type: Basic Vehicle Limited Warranty</p>	Part	Quantity	FERRITE ROUND CABLE FOR HARNESS(2134590-00-A)	1.00	POWER CONVERSION SYSTEM - 48AMP(1777777-T2-G)	1.00																							
Part	Quantity																													
FERRITE ROUND CABLE FOR HARNESS(2134590-00-A)	1.00																													
POWER CONVERSION SYSTEM - 48AMP(1777777-T2-G)	1.00																													
3	<p><b>Concern:</b> Rear LH Tire Replacement</p> <p><b>Repair Notes:</b> Technician lifted up the Vehicle. Removed and replaced lefty rear Tire due to damaged as per customer approval. Balanced and torqued to spec. at this time.</p> <table> <thead> <tr> <th>Correction Tire - Rear - LH (Remove &amp; Replace)</th> <th>Labor Hours</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> </thead> <tbody> <tr> <td></td> <td>0.35</td> <td>35.00</td> <td>0.00</td> <td>35.00</td> </tr> </tbody> </table> <p><b>Parts Replaced or Added</b></p> <table> <thead> <tr> <th>Part</th> <th>Quantity</th> <th>Unit Price</th> <th>Price</th> <th>Adjustment</th> <th>Subtotal</th> </tr> </thead> <tbody> <tr> <td>285/65R20 D 123/120H - GOODYEAR - WRANGLER TERRITORY RT T2(1250242-00-C)</td> <td>1.00</td> <td>500.00</td> <td>500.00</td> <td>0.00</td> <td>500.00</td> </tr> <tr> <td>TIRE DISPOSAL FEE(1025331-00-A)</td> <td>1.00</td> <td>6.00</td> <td>6.00</td> <td>0.00</td> <td>6.00</td> </tr> </tbody> </table> <p style="text-align: right;"><b>Parts Subtotal 506.00</b></p> <p style="text-align: right;">Pay Type: Customer Pay</p> <p><b>Total Parts Amount 506.00</b>  <b>Total Labor Amount 35.00</b>  <b>Labor Hours 0.35</b></p>	Correction Tire - Rear - LH (Remove & Replace)	Labor Hours	Price	Adjustment	Subtotal		0.35	35.00	0.00	35.00	Part	Quantity	Unit Price	Price	Adjustment	Subtotal	285/65R20 D 123/120H - GOODYEAR - WRANGLER TERRITORY RT T2(1250242-00-C)	1.00	500.00	500.00	0.00	500.00	TIRE DISPOSAL FEE(1025331-00-A)	1.00	6.00	6.00	0.00	6.00	<b>541.00</b>
Correction Tire - Rear - LH (Remove & Replace)	Labor Hours	Price	Adjustment	Subtotal																										
	0.35	35.00	0.00	35.00																										
Part	Quantity	Unit Price	Price	Adjustment	Subtotal																									
285/65R20 D 123/120H - GOODYEAR - WRANGLER TERRITORY RT T2(1250242-00-C)	1.00	500.00	500.00	0.00	500.00																									
TIRE DISPOSAL FEE(1025331-00-A)	1.00	6.00	6.00	0.00	6.00																									
4	<p><b>Concern:</b> Loaner Wheel Reunite</p> <p><b>Repair Notes:</b> Closing Loaner Wheel line on this SV so that this Loaner Wheel Reunite doesn't get canceled. Customer received Loaner Wheel from Mobile Tire on 3/21</p> <p><b>Correction Loaner Wheel Reunite</b></p> <p style="text-align: right;">Pay Type: Goodwill-Internal</p>	<b>0.00</b>																												

Service Center hourly rate: USD 230

Notes: To assess your vehicle's Tire Wear and Condition, please see the Tire Care and Maintenance section from the digital Owner's Manual in your car.

All parts are new unless otherwise specified.

Parts Taxable Amount (USD)	506.00
----------------------------	--------